


Unit Type	MHRC2-036, 048, 060-VS-01
CAD Tech	M. LeRoy
Date	JAN 29, 2018
Revision	1.6



MCS-MAGNUM-24
© 2013
REV 8.4

NOTE:
1. Drain shield must be cut at BOTH ends.

- NOTES:**
1. Sensors MUST use shielded cable and shield must not be broken. The shield must be connected only at the Sensor Input terminal block
 2. All sensor inputs are 0 to 5vdc.
 3. Amp input sensors are field wired and must be shielded cable. They generate their own voltage and do not require 5vdc from the MCS unit.
 4. Digital input sensors are field wired and must be shielded cable. The 5vdc is taken out from the sensor terminal and wired through the switch. The jumper must then be set to digital.
 5. Factory wired: _____
Field wired: _____
 6. Digital Sensor Jumper :
Analog Sensor Jumper :